

SERVICE BULLETIN: # SB-10-25-1999

DATE: 25 October 1999

TO: Homebuilders, Maintenance staff, Dealers, Owners, Pilots

AFFECTED PRODUCTS: CH7 Kompress

PRODUCTS / SERIALS: KOMPRESS / ALL

SUBJECT: Electric system defect

INSPECTION: Pre-flight check
50 h. calendar inspection
100 h. calendar inspection
200 h. calendar inspection
300 h. calendar inspection

REPLACEMENT: Immediate
X 50 h. calendar inspection
100 h. calendar inspection
200 h. calendar inspection
300 h. calendar inspection

COMPLIANCE PROCEDURE:

- Disconnect relay between point 15/54 of start block and bulbs-fan breaker.
- Overturn relay between C.B. bulbs-fan and T.C.U. so as to connect them together .
- Disconnect C wire of bulbs-fan breaker and connect it to point 15/54 of start block.