

SERVICE BULLETIN: # SB-R01

DATE: 28 April 2014

AFFECTED PRODUCTS: CH77 Ranabot

PRODUCTS / SERIALS: Ranabot CH77 from 002 to 025


SUBJECT: VERTICAL STABILIZER SUPPORT

INSPECTION: immediately, before the next flight


REPLACEMENT: mandatory

COMPLIANCE PROCEDURE:

Inspect before the next flight the Vertical stabilizer support P/N CH7070200K in the areas under investigation to cracks of metal bending 90 degrees described in the attached photos . The Helisport Helicopters here will replace the part in exchange mode. Ship support to Helisport Helicopters to get the exchange.



Rear view up



Front view down